








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu


XX = AA, XG, ..











Pos.	Part No.	
1	A 861 895 XX	
2	A 861 859 XX	
3	A 861 899 XX	
4	A 861 872 NU	
5	A 861 577 XX	
6	A 861 892 NU	
7	A 960 706 NU	
8	A 861 893 NU	
9	A 861 875 NU	
10	A 960 890 NU	
11	A 963 143 NU	
12	A 7878 XX	
13	A 960 704 NU	20mm
	A 962 476 NU	40mm






Ceratherm C25
A8587..

1225 / A 869 335
Made in Germany





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65 55		I/min 18