





Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικοί Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Teltitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli

XX = AA, AD,



- 1 - B 961852 XX
- 2 - A 963751 NU
- 3 - B 961373 XX
- 4 - B 961374 NU
- 5 - A 861181 NU
- 6 - B 961491 NU
- 7 - B 960883 XX
- 8 - A 964520 NU
- 9 - B 960900 XX
- 10 - B 964550 XX
- B 960853 XX
- 10a - B 961705 XX



B C833 ..





B D077 ..



Ideal Standard

CERABASE

04.2024 / B565246




B C829 ..




B C828 ..

B C827 ..



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<https://www.idealstandard.com>





| | | | | | | | | |
|------------------|------|------|----|----|----|----|----|----|
| P | 50°C | 15°C | 0 | 1 | 2 | 3 | 4 | 5 |
| | | | °C | °C | °C | °C | °C | °C |
| 0,3 MPa 3 bar | 65°C | 15°C | 65 | 63 | 57 | 50 | 44 | 40 |
| | 85°C | 15°C | 85 | 83 | 74 | 64 | 56 | 50 |

| | | | | | |
|---|-----|---------|---------|----|-----------|
| P | bar | 0,5 | MAX. 10 | 5 | Q (3 bar) |
| T | °C | MAX. 80 | 65 | 40 | l/min |
| | | | | | 3,8 |