







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ..

Pos.	Part No.		
1	A 861 405 XX	8	A 861 883 XX
2	A 860 989 XX	9	A 963 952 NU
3	A 861 882 XX	10	A 960 890 NU
4	A 861 872 NU	11	A 963 143 NU
5	A 861 880 XX	12	A 7851 XX
6	A 861 874 NU		A 7877 XX
7	A 861 500 NU	13	A 960 704 NU
			A 962 476 NU





Connect Air


A8740 ..







Ideal Standard

1025 / A 869 342
Made in Germany




Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
www.idealstandard.com





			0	1	2	3	4	5
 0,3 MPa 3 bar	 50°C 65°C 85°C	 15°C 15°C 15°C	50	49	44	40	35	33
			65	63	57	50	44	40
			85	83	74	64	56	50



 bar	 MAX. 10 0,5	 5 1		 (3 bar)
 °C	 MAX. 80	 65 55		 l/min
				21